

Page 1

Friday, September 25, 2009 10:58:57 AM Item ID: D3137-045 Accept Setup Start F **Revision ID:** Stop **Item Name: Bracket Assembly** Start Qty: 4.00 **Start Date:** 9/23/2009 **Cust Item ID:** Required Date: 10/9/2009 Req'd Qty: 4.00 **Customer:** Reference: Run Start Date 09-9-2 **Process Plan:** Tooling: **Approvals:** Date: Stop QC: Date: SPC (Y/N): Date: Reject Sequence ID/ Set Up/ Operation Draw Draw Plan Accept Reject Insp. Number **Work Center ID** Description Rev. Qty Qty Number Stamp **Run Hours** Code **Draw Nbr** Revision Nbr D3137 Rev F 100 0.00 BAND SAW 0 Bandsaw 0.00 Memo Jeaspa Bandsaw Cut blanks: (.500" x 2.000") 4.400" long 110 0.00 HAAS CNC VERTICAL MACHINING #1 0.00 HAAS 1 Memo HAAS CNC vertical machine #1 T-Machine D3137-9 as per Folio FA621 and Dwg D3137 Identify as D3137-9□2-Deburr□3-Scribe batch number 120 QC2- Inspect parts off machine FAI/FAIB 0.00 QC 0.00 Memo Quality Control

Friday, September 25, 2009 10:58:57 AM

Page 2

Item ID:

D3137-045

Accept

Setup Start

Stop

Revision ID:

F

Required Date: 10/9/2009

Item Name:

Bracket Assembly

Start Date:

9/23/2009

Start Oty: 4.00

Req'd Qty: 4.00



Date:

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

0.00

SPC (Y/N):

Date:

Date:

Start Run

Stop



Sequence ID/ Work Center ID

130

QC

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Set Up/ **Run Hours**

0.00 a. Logloloz

Draw Number

Plan Draw Rev. Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

140

Small Fab

Small Fab

Small Fab

Memo

Memo

0.00

0.00

Assemble D3137-045 as per Dwg D3137

Eporpo/07

150

Quality Control

QC5- Inspect part completeness to step on W/O

2) 50/6/67

Work Order ID 52371

Page 3

Item ID:

D3137-045

Friday, September 25, 2009 10:58:57 AM

Accept

Setup Start

Stop

F **Revision ID:**

Item Name:

Bracket Assembly

Start Date:

9/23/2009

Start Qty: 4.00

Req'd Qty: 4.00 Required Date: 10/9/2009



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

Stop

Date:

SPC (Y/N):

Draw

Number

Date: Draw

Rev.

Plan Code

Accept

Qty

Reject Qty

Reject Number

Insp. Stamp

Sequence ID/ Work Center ID

160



Packaging Packaging

Operation **Description**

Identify as per dwg & Stock Location:

Memo

Memo



Set Up/ **Run Hours**

0.00

0.00

EN.10-0+

170

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

09/10/07

in 31-10-07

Picklist Print

Friday, September 25, 2009 10:58:57 AM

Work Order ID: 52371

D3137-045RevF

Parent Item Name: Bracket Assembly

Parent Item:



Start Date: 9/23/2009

Required Date: 10/9/2009

Start Otv: 4.00

Required Otv: 4.00

Comments:								\$	Start Qty: 4.00]	Required Qty: 4.	00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
MS24694-S101 Purchased			No			100	Each	104.0000	4.0000	Ba fr	2/07	
				<u>Wareho</u>	use	Loc	Oty	Loc Code				
•				Loca	ation							
				Main Wa	arehouse							
,				ST			104					
					103338		5		_	Ш		
03137-3RevF		Manuelantum	No		110363	140	99 Each	23.0000	4.0000	7		
HIII III III III III III III III III II		Manufactured	NO			140	Edoli	23.0000	4.0000	1502/	10/07	
uide				Wareho Loca	use ation	Loc	Oty	Loc Code				
				Main Wa	arehouse							
				ST			23		_			
					39449		9		_	4		
					39628	140	14	44 0000				
03137-5RevF		Manufactured	No			140	Each	41.0000	4.0000	£509/	10/07	
'asher				<u>Wareho</u>	use	Loc	Otv	Loc Code				
					ation							
				Main W	arehouse							
				ST			41					
					10536		1		_			
					24547		2					
					42270		6		_	4		
					46740		32		_			

Picklist Print

Friday, September 25, 2009 10:58:57 AM

Work Order ID: 52371

Parent Item: D31

D3137-045RevF

Parent Item Name: Bracket Assembly

Comments:



Start Date: 9/23/2009

Required Date: 10/9/2009

Page 2

Start Qty: 4.00

Required Qty: 4.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M174B0.500X02.000		Purchased	No			140	f	84.7800	1.5436			
								**				

17-4 SS Bar .500 x 2.00

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
MAT	84.78		
100843	13.01		
103089	20.25		15436 DL 09/10/04
14932	26.63		
19572	24.89		

DART AEROSPACE LTD	Work Order:	5237/
Description: Bracket	Part Number:	D3137-9
Inspection Dwg: D3137 Rev: F		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.435	+/-0.010	.436	~			
0.615	+/-0.010	062.	V		,	2.1
. 0.380	+/-0.010				NID	1/109.10.0
0.200	+/-0.010	.ω	~		/	
0.600	+/-0.010	ad,	V			
0.780	+/-0.010	.784	V			
0.500	+/-0.010	.70C	✓			
0.063	+/-0.010	640,	S			
R0.062	+/-0.010	2.043	7			
0.162	+/-0.010	3,40	7			
Ø0.560	+0.008/-0.001	002.B	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		,	
0.595	+/-0.010			- ^	VA Chi	10910.07
4.21	+/-0.030	4,20	/			
3.770	+/-0.010	3.97	V			
1.280	+/-0.010	1,275	V			
0.700	+/-0.010	. 199	V			·
1.90	+/-0.030	1.89	7			
100°	+/-0.5°	100°				· · · · · · · · · · · · · · · · · · ·
2.14	+/-0.030	2.13	\ <u></u>			
0.262	+/-0.010	506.	\ \ \			
R0.25	+/-0.030	1.25)			
0.032	+/-0.010	.037	~			

Measured by:	Audited by:	and	Prototype Approval:	N/A
Date: 02/00/07	Date:	04/10/07	Date:	N/A

Rev	Date	Change	Revised by Approved
Α	06.08.30	New Issue P/O D3137-045	KJ/JLM ,
В	08.12.02	Dwg Rev updated	KJ/DD 💉



8

APPROVED

08.05.30

DE APPR.

DATE

TITLE

BRACKET ASSEMBLY

COPYRIGHT © 2002 BY DART AEROSPA CE LTD

THE DOCUMENT IS PRIVATE AND COMPECTIFUL AND IS MAPPLED ON THE EXPRESS CONDITION
HOT TO BE USED FOR ANY PLANCES ON COPED ON COMMANDED TO TO ANY OTHER PRIVACE
WHITTHE PROMESSION FROM DAY ARROPANCE.

SCALE

QTY041 X	QTY043 X 1 1 1	X 1 1 1 1 1	PART NUMBER D3137-041 D3137-043 D3137-045 D3137-1 D3137-3 D3137-5 D3137-7 D3137-9 MS24894-S101	DESCRIPTION BRACKET ASSEMBLY BRACKET ASSEMBLY BRACKET ASSEMBLY BRACKET GUIDE WASHER BRACKET BRACKET SCREW	D313 WASI	37-5 HER	
1 1 1	1 1 1	1 1	D3137-041 D3137-043 D3137-045 D3137-1 D3137-3 D3137-5 D3137-7 D3137-9	BRACKET ASSEMBLY BRACKET ASSEMBLY BRACKET GUIDE WASHER BRACKET BRACKET	D313 WASI	37-5 HER	
1 1 1	1 1 1	1 1	D3137-043 D3137-045 D3137-1 D3137-3 D3137-5 D3137-7 D3137-9	BRACKET ASSEMBLY BRACKET ASSEMBLY BRACKET GUIDE WASHER BRACKET BRACKET	D313 WASI	37-5 HER	
1	1 1 1	1 1	D3137-045 D3137-1 D3137-3 D3137-5 D3137-7 D3137-9	BRACKET ASSEMBLY BRACKET GUIDE WASHER BRACKET BRACKET	D313 WASI	37-5 HER	
1	1	1 1	D3137-1 D3137-3 D3137-5 D3137-7 D3137-9	BRACKET GUIDE WASHER BRACKET BRACKET	D313 WASI	37-5 HER	
1	1	1	D3137-3 D3137-5 D3137-7 D3137-9	GUIDE WASHER BRACKET BRACKET	D313 WASI	37-5 HER	
1	1	1	D3137-5 D3137-7 D3137-9	WASHER BRACKET BRACKET	D313 WASI	37-5 HER	
	1	1	D3137-7 D3137-9	BRACKET BRACKET	D313 WASI	37-5 HER	
1			D3137-9	BRACKET	D313 WASI	37-5 HER	
1	1				D313 WASI	37-5 HER	
1	1	1	MS24694-S101	SCREW	WASI	HER	ł
1	1	1	MS24694-S101	SCREW			
							D3137-5
				-MS24694-S101 SCREW	D3737-3 GUIDE — MS SCI	524694-S101 D3737-3 GUIDE GUIDE	WASHER
		E	D3137-1 BRACKET	DM07.5			MS24694-S101 SCREW
				D3137-5 WASHER			
					D3137-7 BRACKET	D3137-9 BRACKET)
			D3137-041 BRACKE	T ASSEMBLY	D3137-043 BRACKET ASSEMBLY	<u>D3137-045 BRACKET</u>	ASSEMBLY
DENTIFICA WEIGHT: 0.1 0.3:	TION: N/A	ART QSI 018 S OTHERW :: N/A	UNLESS OTHERWISE NOTED ISE NOTED		RELEASED OS: 06 16/M	DRAWN ALS HAWKESB ORAWING NO. D3137 APPROVED DE APPR. BRACKET AS	AEROSPACE LTD BURY, ONTARIO, CANADA REV. F SHEET 2 OF 5 SCALE SSEMBLY NTS 2 2002 BY DART AEROSPACE LTD OR COMEN ON COMEN HONOLIT FOR OR COMEN WITHOUT PRESSEN WITH PRESSEN WITH PRESSEN W

